: DART 4-MAN 3-POINT AFT FACING SHOULDER

HARNESS ASSEMBLY

: D412702045B

: IIN D412-702 REV E

Monday, 03/11/2008 1:08:11 PM

Dete: Julie Dawson User:

Process Sheet

Drawing Name

Part Number

Drawing Number

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

Job Number

: 43156

Estimate Number

: 12867

P.O. Number

This Issue

: 03/11/2008 Prsht Rev.

First Issue

: NC

: // : 42792

Previous Run

Written By

Checked & Approved By

Comment

: est rev A 07.05.10 new issue EC

Est Rev:B 07-07-06 As per Rev E JLM

: SMALL /MED FAB

: N/A **Project Number** ; E

Drawing Revision

Material **Due Date**

: 05/11/2008

Qty:

1 Um:

Each

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: DOCUMENT CONTROL

1.0

3.0

4.0

JUD 08.11,03

Photocopy bluefile & type labels per PPP D412-702-045B CHG003

D412702111B 2.0

Harness Assembly

Comment: DOCUMENT CONTROL

Comment: Qty.: 2.0000 Each(s)/Unit

2.0000 Each(s) Total:

HARNESS ASSEMBLY B42793

D412702113B Harness Assembly

Comment: Qty.:

2.0000 Each(s)/Unit

Total: 2.0000 Each(s)

HARNESS ASSEMBLY

D3572041

Guide Assembly

Comment: Qty.: 2.0000 Each(s)/Unit

M40532

2.0000 Each(s)

GUIDE ASSEMBLY

Total:

AN416A

5.0

Bolt

Bolt

Comment: Qty.:

2.0000 Each(s)/Unit

Total:

2.0000 Each(s)

Dart Aerospace Lte

W/O:			W	ORK ORDER CHANG	ES							
DATE	STEP	PROCEDURE CHANGE				,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector		
										·		
Part No:		PAR #:	Fault Category: NC			NCR: Yes No DQA:				Date:		
Resolution:			Disposit	Disposition:			sed:		Date:			
NCR:	,		WORK OR	DER NON-CONFORM	ANCE (N	CR)						
DATE	STEP	Description of NC			tion B	Verification				Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng		ate			Chief Eng	QC Inspector		
							1					
· · · - · · · · · · · · · · · · · · · ·							ļ					
										*		

NOTE: Date & initial all entries

	day, 03/11/2008 1:08:11 PM Dawson	Process Sheet	
Customer:	CU-DAR001 Dart Helicopters Services	Drawing Name: DART 4- ASSEME	MAN 3-POINT AFT FACING SHOULDER HARNESS
Job Number:	43156	045B	
Job Number:		·	
Seq. #:	Machine Or Operation:	Description	
6.0 Comme	nt: Qty.: 4.0000 Each(s)/Unit Total :	M/04438 4.0000 Each(s)	s\(\emptyselon \)
7.0	BOLT AN960JD416	Washer	
7.0	ANSOUS CONTRACTOR OF THE PROPERTY OF THE PROPE	Waller	
Comme	nt: Qty.: 20.0000 Each(s)/Unit Total: Washer batch: MIDSSJ7	20.0000 Each(s)	50
8.0	MS21042L4*	Nut	
Comme	nt: Qty.: 6.0000 Each(s)/Unit Total : Nut batch: 15945	6.0000 Each(s)	Sp
9.0	QC4-	INSPECT 100% KITS FOR COMPLETEN	ESS
10.0	nt: INSPECT 100% KITS FOR COMPLETE PACKAGING 1	PACKAGING RESOURCE #1	solutor (x)
Comme	nt: PACKAGING RESOURCE #1 Identify and pack for shipping as per PF	PP D412-702-0#5B \CHG003	
	Location: 5 \ PPP Rev:	8/11/4	sφ
11.0	QC21	FINAL INSPECTION/W/O RELEASE	08/11/05
Job Completion	nt: FINAL INSPECTION/W/O RELEASE		mF 08-11-0

D ui. (/ (0)	Jopass	, = (4								
W/O:			V	ORK ORDER CHANGE	S					
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
					:					
			·····							
Part No: PAF		PAR #:	Fault Category: N			s No D	QA:	Date:		
Resolution:			Disposition:			Closed: _		Date:		
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (NO	CR)				
DATE	STEP	Description of NC Section A		Corrective Action Section		Ver	ification	n Approval	Approval	
DATE			Initial Chief Eng	Action Description Chief Eng	on Sign & Date		ection C	Chief Eng	QC Inspector	
				*						

NOTE: Date & initial all entries